



KAILUA BEACH PARK - KAILUA, HI

PROJECT DESCRIPTION

The walls and bathroom facility exterior at the popular Beach Park in Kailua, Hawaii were deteriorating and in need of complete restoration in order to accommodate the large number of visitors each week. Project owners decided to utilize Arisfor WallGuard® in order to restore the existing structures to like-new condition. Workers applied WallGuard® with a trowel, noticing its **easy application process, quick dry time and superior finish**. The WallGuard® also came in handy due to its UV and water resistance, which is important due to its proximity to the beach.

KEY POINTS

- Quick Dry Time
- Superior Durability
- Superior Finish

DETAILS

Date: 2017

Location: Kailua, HI

Product: Arisfor WallGuard®

Application: Trowel

Contact us for more details