



POLICE STATION - KAPOLEI, HI

PROJECT DESCRIPTION

The molding along the wall of this Police Station were deteriorating from being frequently brushed with officer utility belts as they walked past. **In result, they sought out a superior, easy to apply, and quick drying coating that could resist the wear and tear of a busy police station.** Owners and specifiers chose to use Arisfor WallGuard® to repair and restore the molding while also adding **superior protection, abrasion resistance and durability.** After restoring with WallGuard®, **the police station was able to continue its normal operations very quickly after application.**

KEY POINTS

- Quick Dry Time
- Provides Long-Term Durability
- Superior Finish

DETAILS

Date: 2013

Location: Kapolei, HI

Product: Arisfor WallGuard®

Application: Trowel

Contact us for more details