



## COUNTRY CLUB WALKWAY - GROVE CITY, PA

### PROJECT DESCRIPTION

The Grove City Country Club's exterior concrete walkway into the main entrance of their building was badly cracked in several places. This issue prompted owners to search for an easy and cost effective restoration method that would not leave the walkway out of service for a long period of time. **The Grove City Country Club chose to use Arisfor ToughDeck® in order to fix the cracking issues and restore the walkway to a "like new" condition, without a long application and dry time.**

### KEY POINTS

- Quick Dry Time
- Provides Long-Term Durability
- Superior Finish

### DETAILS

**Date:** 2017

**Location:** Grove City, PA

**Product:** Arisfor ToughDeck®

**Application:** Trowel

Contact us for more details