



## PUBLIX - GULF BREEZE, FL

### PROJECT DESCRIPTION

Publix, a commercial shopping plaza, needed to repair approximately 6000 square feet of exterior stucco damage and paint the entire exterior. In addition to the block cracking in certain areas, the building's stucco was chipping and peeling off the substrate. Harrison Contracting was hired for this undertaking and chose to use WallGuard to patch and repair all of this building's stucco damage. **Arisfor WallGuard offers superior toughness and durability to exterior walls, as well as provides a longer lasting finish.** This building's **exposure to the coastal elements in Florida will benefit greatly from both advantages.** In addition, by using the WallGuard product, **the owners of this shopping plaza saved more than \$10,000 by not replacing the stucco.**

### KEY POINTS

- Viable Return on Investment
- Provides Long-Term Durability
- Weather Resistant

### DETAILS

**Date:** February 15, 2018

**Location:** Gulf Breeze, FL

**Product:** Arisfor WallGuard®

**Application Method:** Trowel

Contact us for more details